

STRADBROKE HEALTH CENTRE  
ASBESTOS REPORT 7<sup>th</sup> June 2021

A detailed survey undertaken in 2010 highlighted that chrysotile was present in the cement under cloaking of the roof.

The risk was identified as low – 6.

The condition of the under cloaking is monitored regularly.

There has been no deterioration in the material.

2010 details:

**Survey Details**

**Entry Number**            20  
**Lead Surveyor**            Philip  
**Jenkins Inspection Type**    Type  
*II Asbestos Survey*  
**Inspection Date** 13 January 2010

**Item Details**

<b>Area Title</b>	External
<b>Floor/Level</b>	Ground Floor
<b>Product Type</b>	Cement Products
<b>Item Description</b>	S17
<b>Estimated Extent</b>	40 m
<b>Labelled</b>	No
<b>Product Description</b>	Cement under cloaking



**Material Algorithm**

**Wgt Material Categories**

<b>Product Type</b>	Cement Products	1	<b>Material Factor</b>	<b>Potential For Fibre Release</b>
<b>Treatment</b>	None	3	<b>&gt;= 10</b>	High
<b>Damage Extent</b>	Low	1	<b>7 - 9</b>	Medium
<b>Asbestos Type</b>	Chrysotile	1	<b>5 - 6</b>	Low
<b>Material Factor Rating</b>		<b>6</b>	<b>0 - 4</b>	Very Low

Odile Wladon (Clerk) on behalf of Stradbroke Parish Council